



Fuses are F2 and F3. These are NANO2 type fuses.

F2 protects the Motors and On-Board Power Supply.

F3 protects the Extruder and Fan Outputs.

F4 protects the Heated Bed.