

Seemecnc - 4 Axis Board Wiring Diagram





3 12v Yellow Wires from PS

3 Ground Black Wires from PS

Black
Green
Blue
Red

Repeat for Y, Z,
Extruder



Black
Green

1 Ground Wire from PS – Double up with Resistor Ground

2 12v Yellow Wires from PS

Ground - Double up with Ground from PS

Heat Resistors

Thermostat Sensor



Replace R5 with Jumper for Higher Temps